



# Canadian Coast Guard

**Home** 

> MCTS

> Notices to Shipping (NOTSHIP)

# Written Notices to Shipping - Maritimes

## **Search Notships**

Series All Series
Area All Areas

Warning: Do not select dates to see all NOTSHIPs presently in effect. Beginning and end dates are based on dates of issuance only.

| Date of issuance of the notice (Optional) between 22/09/2017 |         |  | 09/2017 and |  |
|--|---------|--|-------------|--|
| Display  |         |  |             |  |
| Detail   | Summary |  |             |  |

Search

## **BAY OF FUNDY - N.S.**

M2136/17 - BAY OF FUNDY - N.S. - Chart 4118 - Issued on 2017-10-19
METEGHAN OUTER LIGHT BUOY HC3 - LL 239.3 REPORTED GONE FROM ADVERTISED POSITION.

#### **BAY OF FUNDY - SAINT JOHN HARBOUR AND APPROACHES**

M2066/17 - BAY OF FUNDY - SAINT JOHN HARBOUR AND APPROACHES - Chart 4117 - Issued on 2017-10-06

NEW LIMITING DEPTHS REPORTED AS FOLLOWS: PIER 3 A/B: FROM 10.4 METRES TO 10.0 METRES RODNEY SLIP A: FROM 12.2M TO 10.0 METRES

### **CAPE BRETON ISLAND**

M2137/17 - CAPE BRETON ISLAND - Chart 4377 - Issued on 2017-10-19 BAR REEF LIGHT AND BELL BUOY JJ3 - LL 764 REPORTED EXTINGUISHED.

M2126/17 - CAPE BRETON ISLAND - Chart 4278 - Issued on 2017-10-18 CHANNEL MARKERS IN ST PATRICKS CHANNEL MAY BE UNRELIABLE.

M2056/17 - CAPE BRETON ISLAND - Chart 4278 - Issued on 2017-10-05
LITTLE NARROWS LIGHT BUOY A29 - LL 829,3 REPORTED OFF ADVERTISED POSITION.

#### CHALEUR BAY

M2161/17 - CHALEUR BAY - Chart 4920 - Issued on 2017-10-24
PETIT-ROCHER BREAKWATER LIGHT - LL 1339.2 PERMANENTLY ESTABLISHED IN POSITION 47 46 55.2N 065
42 30.0W. LIGHT CHARACTERISTICS; GREEN FLASH 01 SECOND ECLIPSE 03 SECONDS. 1 PORT SIDE DAY

BEACON.

M2159/17 - CHALEUR BAY - Chart 4920 - Issued on 2017-10-24
PETIT-ROCHER BREAKWATER LIGHT - LL 1339.2 NOMINAL RANGE PERMANENTLY CHANGED TO 4 NM.

M2073/17 - CHALEUR BAY - Chart 4426 - Issued on 2017-10-10
DALHOUSIE HARBOUR LIGHT BUOY EX2 - LL 1343.2 REPORTED OFF ADVERTISED POSITION.

## **GULF OF ST. LAWRENCE**

M1970/17 - GULF OF ST. LAWRENCE - Chart - Issued on 2017-09-22

IN ORDER TO PROMOTE NAVIGATION SAFETY AND PROTECTION OF THE MARINE ENVIRONMENT DUE TO AN INCREASED PRESENCE OF NORTH ATLANTIC RIGHT WHALES IN THE GULF OF ST. LAWRENCE, ALL VESSELS OF 65 FEET (19.8M) OR LONGER ARE INSTRUCTED TO PROCEED AT A SPEED NOT EXCEEDING 10.0 KNOTS OVER THE GROUND IN THE ST. LAWRENCE RIVER AND THE GULF OF ST. LAWRENCE BETWEEN THE FOLLOWING COORDINATES: 47° 10' N 062° 00' W; 47° 10' N 065° 00' W; 50° 20' N 065° 00' W; 50° 20' N 062° 00' W.

FAILURE TO COMPLY WITH THIS SPEED RESTRICTION COULD LEAD TO ENFORCEMENT ACTION UNDER SECTION 7 OF THE COLLISION REGULATIONS.

MARINERS ARE REQUESTED TO REPORT ALL OBSERVATIONS OF ENTANGLED, DEAD, OR INJURED WHALES TO THE CCG ON VHF CH. 16 OR TO THE MARINE ANIMAL RESPONSE SOCIETY AT 1-866-567-6277 FOR THE SOUTHERN PART OF THE GULF OF ST. LAWRENCE, TO THE WHALE RELEASE AND STRANDINGS AT 1-709-895-3003 FOR NEWFOUNDLAND AND LABRADOR AND TO MARINE MAMMAL EMERGENCIES AT 1-877-722-5346 FOR THE OUEBEC SECTOR.

SIGHTINGS OF LIVE, FREE-SWIMMING WHALES SHOULD BE REPORTED TO (902)-440-8611 OR EMAIL:XMARWHALESIGHTINGS@DFO-MPO.GC.CA.

#### **GULF OF ST. LAWRENCE - N.B.**

M2108/17 - GULF OF ST. LAWRENCE - N.B. - Chart 4913 - Issued on 2017-10-16 FOX DENS GULLY LIGHT BUOY TK15 - LL 1262.75 REPORTED GONE FROM ADVERTISED POSITION.

M2050/17 - GULF OF ST. LAWRENCE - N.B. - Chart 4906 - Issued on 2017-10-05 VAL COMEAU WHARF LIGHT - LL 1239.8 TEMPORARILY DISCONTINUED.

M2024/17 - GULF OF ST. LAWRENCE - N.B. - Chart 4913 - Issued on 2017-10-02 STE- MARIE-SUR-MER BREAKWATER LIGHT - LL 1262 PERMANENTLY REPOSITIONED TO 47 46 40.6 N 064 33 49.7 W EQUIPED WITH A STARBOARD HAND DAYBEACON

M1971/17 - GULF OF ST. LAWRENCE - N.B. - Chart 4913 - Issued on 2017-09-24 ON SEPTEMBER 25, 2017, DREDGING OPERATIONS WILL COMMENCE IN THE CHANNEL AT THE INTERIOR OF FOX DENS GULLY (PIGEON HILL GULLY) N.B.

ON SITE CONTACT: ANDY SCOTT (902) 222-3504.

MARINERS ARE REQUESTED TO PROCEED WITH CAUTION IN THIS AREA.

### **GULF OF ST. LAWRENCE - P.E.I.**

M2051/17 - GULF OF ST. LAWRENCE - P.E.I. - Chart 4023 - Issued on 2017-10-05
NAUFRAGE HARBOUR EAST BREAKWATER LIGHT - LL 1040.2 PERMANENTLY CHANGED TO 3.05 METRE
ALUMINUM SWINGPOLE STRUCTURE. LIGHT CHARACTERISTICS GREEN FLASH 1 SECOND ECLIPSE 3 SECONDS.
NOMINAL RANGE 5.8 NAUTICAL MILES. PORT DAYMARK ADDED.

M2038/17 - GULF OF ST. LAWRENCE - P.E.I. - Chart 4425 - Issued on 2017-10-03 COVEHEAD HARBOUR LIGHT BUOY JJ4 - LL 1050.12 REPORTED GONE FROM ADVERTISED POSITION.

### HALIFAX HARBOUR AND APPROACHES

M2114/17 - HALIFAX HARBOUR AND APPROACHES - Chart 4237 - Issued on 2017-10-17 DUNCAN REEF LIGHT BUOY H1 - LL 512.5 TEMPORARILY EQUIPPED WITH AIS. MMSI 993161044. MARINERS ARE ENCOURAGED TO SUBMIT THEIR COMMENTS TO HALIFAX COAST GUARD RADIO, OR HALIFAX TRAFFIC.

M2094/17 - HALIFAX HARBOUR AND APPROACHES - Chart 4203 - Issued on 2017-10-13
HALIFAX HARBOUR SMART BUOY - LL 521.5 PERMANENTLY REPOSITIONED TO 44 33 .3549 N 063 32 .6442 W

## **NAVAREA IV**

M2091/17 - NAVAREA IV - Chart - Issued on 2017-10-12
PT ESCUMINAC DGPS 319 KHZ OFF THE AIR UNTIL FURTHER NOTICE.

#### NORTHUMBERLAND STRAIT - N.B.

**M2147/17** - NORTHUMBERLAND STRAIT - N.B. - Chart 4905 - Issued on **2017-10-20** FROM OCTOBER 23, 2017 AND UNTIL FURTHER NOTICE, DREDGING OPERATIONS WILL TAKE PLACE AT THE HARBOUR AT LES ABOITEAUX WHARF, NEW BRUNSWICK.

LOADING SITE: 46°13' 49.30"N 64° 17' 51.49"W DISPOSAL SITE: 46°13' 56"N 64°18' 03"W

MARINERS ARE REQUESTED TO EXERCISE CAUTION IN THIS AREA.

**M2145/17** - NORTHUMBERLAND STRAIT - N.B. - Chart 4498 - Issued on **2017-10-20** A YELLOW CAUTIONARY BUOY IN APPROXIMATE POSITION 45 53.604N 063 37.411W IS MARKING A HAZARD. MARINERS ARE REQUESTED TO EXERCISE CAUTION IN THE AREA.

M2117/17 - NORTHUMBERLAND STRAIT - N.B. - Chart 4909 - Issued on 2017-10-17 SHEDIAC WHARF LIGHT - LL 1110.5 PERMANENTLY ESTABLISHED IN POSITION 46 14 30.03N 064 31 48.41W. LIGHT CHARACTERISTICS; FLASH 2 SECONDS, ECLIPSE 4 SECONDS. DAYMARK RED/WHITE/RED.

## **NORTHUMBERLAND STRAIT - N.S.**

**M2149/17** - NORTHUMBERLAND STRAIT - N.S. - Chart 4498 - Issued on **2017-10-21** PUGWASH CHANNEL LIGHT BUOY UK18 - LL 934 REPORTED EXTINGUISHED.

M2148/17 - NORTHUMBERLAND STRAIT - N.S. - Chart 4405 - Issued on 2017-10-20 TONEY RIVER LIGHT BUOY SU1 - LL 919.6 REPORTED GONE FROM ADVERTISED POSITION.

M2124/17 - NORTHUMBERLAND STRAIT - N.S. - Chart 4483 - Issued on 2017-10-17 CARIBOU HARBOUR INNER RANGE REAR LIGHT - LL 916.35 PERMANENTLY DISCONTINUED.

**M2123/17** - NORTHUMBERLAND STRAIT - N.S. - Chart 4483 - Issued on **2017-10-17** CARIBOU HARBOUR INNER RANGE FRONT LIGHT - LL 916.3 PERMANENTLY DISCONTINUED.

**M2079/17** - NORTHUMBERLAND STRAIT - N.S. - Chart 4437,4483,448302 - Issued on **2017-10-10** AS A RESULT OF A RECENT SOUNDING SURVEY NEAR PICTOU, NOVA SCOTIA, THE FOLLOWING DEPTH CHANGES WERE IDENTIFIED:

# DEPTH /COORDINATES 1 0.2 45-46-05.025217N, 062-46-57.777034W

2 3.4 45-46-06.140900N, 062-45-09.246865W

3 3.5 45-46-03.083942N, 062-43-39.901595W

```
4 0.5 45-45-50.227450N, 062-43-06.363099W
5 2.3 45-46-12.211400N, 062-42-29.883602W
6 1.7 45-46-09.666513N, 062-41-24.631582W
7 1 45-45-57.941082N, 062-41-27.139394W
8 3.5 45-46-02.114583N, 062-40-37.186360W
9 1.2 45-45-34.363949N, 062-40-44.501683W
10 -0.2 45-45-05.098415N, 062-41-05.662786W
11 1.4 45-44-54.179070N, 062-41-46.953160W
12 0.3 45-44-41.330042N, 062-42-40.664284W
13 1.7 45-44-31.874162N, 062-42-41.457960W
14 1.3 45-44-25.502239N, 062-44-17.777465W
15 1.5 45-44-23.571658N, 062-42-41.488286W
16 1.3 45-44-34.959036N, 062-41-45.446051W
17 1.1 45-44-21.281361N, 062-41-14.471971W
18 1.3 45-44-19.712605N, 062-41-13.460907W
19 0.3 45-43-45.836697N, 062-39-41.465974W
20 -0.1 45-44-49.836376N, 062-40-33.345086W
21 -0.3 45-44-54.871354N, 062-40-22.887487W
22 0.6 45-44-55.483125N, 062-39-49.873442W
23 0.8 45-44-32.581459N, 062-38-52.344425W
24 0.6 45-44-20.629059N, 062-38-34.827663W
25 -0.6 45-44-00.085382N, 062-38-44.128268W
26 -0.4 45-43-45.835566N, 062-39-15.749281W
27 1.6 45-43-24.091904N, 062-38-23.329342W
28 1.4 45-43-09.105489N, 062-38-01.607594W
29 1 45-42-38.028525N, 062-38-08.264173W
30 1.6 45-42-29.672179N, 062-38-22.887300W
31 6.8 45-44-56.077934N, 062-34-25.105233W
32 7 45-45-35.779711N, 062-35-14.675840W
33 10.9 45-45-31.640208N, 062-37-20.472650W
34 9.9 45-45-32.115579N, 062-37-38.498157W
35 5.9 45-46-16.187080N, 062-38-41.001093W
36 9.8 45-46-51.545682N, 062-41-31.307735W
37 8.5 45-47-17.411902N, 062-42-39.290121W
38 6.9 45-47-30.082496N, 062-42-40.813442W
39 8.1 45-47-36.038384N, 062-42-31.639326W
40 9.1 45-47-36.252614N, 062-42-01.410705W
41 10.4 45-47-57.609191N, 062-40-07.252932W
42 9.9 45-48-18.257086N, 062-39-21.779871W
43 2.6 45-47-47.353850N, 062-38-19.745257W
44 4.7 45-47-40.811197N, 062-34-33.295271W
45 -0.8 45-48-03.462486N, 062-33-35.724576W
46 0.3 45-49-04.322729N, 062-30-22.444441W
47 8.8 45-50-24.740714N, 062-30-40.589089W
48 9.4 45-50-25.444286N, 062-31-15.594168W
49 9.8 45-50-38.836235N, 062-31-45.544381W
50 0.1 45-49-45.366604N, 062-32-38.291943W
51 3 45-49-50.115809N, 062-33-06.175563W
52 0.4 45-49-29.435277N, 062-33-26.737477W
53 -0.7 45-49-16.050806N, 062-35-36.721568W
```

NOTE THAT DEPTHS ARE BELOW CHS CHART DATUM AND HORIZONTAL POSITIONS ARE BASED ON NAD83.

M1993/17 - NORTHUMBERLAND STRAIT - N.S. - Chart 4443 - Issued on 2017-09-28
THE CANADIAN COAST GUARD PROPOSES TO PERMANENTLY DISCONTINUE TRENTON (EAST RIVER) RANGE
REAR LIGHT - LL 911. COMMENTS ON THIS ACTION ARE SOLICITED FROM MARINERS AND OTHER INTERESTED
PARTIES, WITHIN THREE MONTHS OF THIS NOTICE.

COMMENTS SHOULD BE DIRECTED TO:

SUPERINTENDENT, AIDS TO NAVIGATION

CANADIAN COAST GUARD P.O. BOX 5667 ST. JOHN'S NL A1C 5X1

TELEPHONE: 709-772-6131

EMAIL: RENEE.POPE@DFO-MPO.GC.CA

ANY OBJECTIONS RAISED MUST STATE THE FACTS ON WHICH THEY ARE BASED AND SHOULD INCLUDE SUPPORTING INFORMATION ON SAFETY, COMMERCE AND PUBLIC BENEFIT.

M1992/17 - NORTHUMBERLAND STRAIT - N.S. - Chart 4443 - Issued on 2017-09-28
THE CANADIAN COAST GUARD PROPOSES TO PERMANENTLY DISCONTINUE TRENTON (EAST RIVER) RANGE FRONT LIGHT - LL 910. COMMENTS ON THIS ACTION ARE SOLICITED FROM MARINERS AND OTHER INTERESTED PARTIES, WITHIN THREE MONTHS OF THIS NOTICE.

#### COMMENTS SHOULD BE DIRECTED TO:

SUPERINTENDENT, AIDS TO NAVIGATION CANADIAN COAST GUARD P.O. BOX 5667 ST. JOHN'S NL A1C 5X1

TELEPHONE: 709-772-6131

EMAIL: RENEE.POPE@DFO-MPO.GC.CA

ANY OBJECTIONS RAISED MUST STATE THE FACTS ON WHICH THEY ARE BASED AND SHOULD INCLUDE SUPPORTING INFORMATION ON SAFETY, COMMERCE AND PUBLIC BENEFIT.

M1991/17 - NORTHUMBERLAND STRAIT - N.S. - Chart 4443 - Issued on 2017-09-28 THE CANADIAN COAST GUARD PROPOSES TO PERMANENTLY DISCONTINUE EAST RIVER RED SPAR BUOY SJ48. COMMENTS ON THIS ACTION ARE SOLICITED FROM MARINERS AND OTHER INTERESTED PARTIES, WITHIN THREE MONTHS OF THIS NOTICE.

## COMMENTS SHOULD BE DIRECTED TO:

SUPERINTENDENT, AIDS TO NAVIGATION CANADIAN COAST GUARD P.O. BOX 5667 ST. JOHN'S NL A1C 5X1

TELEPHONE: 709-772-6131

EMAIL: RENEE.POPE@DFO-MPO.GC.CA

ANY OBJECTIONS RAISED MUST STATE THE FACTS ON WHICH THEY ARE BASED AND SHOULD INCLUDE SUPPORTING INFORMATION ON SAFETY, COMMERCE AND PUBLIC BENEFIT.

#### **NORTHUMBERLAND STRAIT - P.E.I.**

M2152/17 - NORTHUMBERLAND STRAIT - P.E.I. - Chart 4419 - Issued on 2017-10-23
THE CANADIAN COAST GUARD PROPOSES TO PERMANENTLY DISCONTINUE SOURIS EAST GREEN CAN BUOY NA5. COMMENTS ON THIS ACTION ARE SOLICITED FROM MARINERS AND OTHER INTERESTED PARTIES, WITHIN THREE MONTHS OF THIS NOTICE.

COMMENTS SHOULD BE DIRECTED TO:

SUPERINTENDENT, AIDS TO NAVIGATION CANADIAN COAST GUARD P.O. BOX 5667 ST. JOHN'S NL A1C 5X1 TELEPHONE: 709-772-6131

EMAIL: RENEE.POPE@DFO-MPO.GC.CA

ANY OBJECTIONS RAISED MUST STATE THE FACTS ON WHICH THEY ARE BASED AND SHOULD INCLUDE SUPPORTING INFORMATION ON SAFETY, COMMERCE AND PUBLIC BENEFIT.

M2112/17 - NORTHUMBERLAND STRAIT - P.E.I. - Chart 4460 - Issued on 2017-10-16
AS THE RESULT OF A RECENT SOUNDING SURVEY IN NORTH RIVER, PRINCE EDWARD ISLAND, THE FOLLOWING SHOAL DEPTH WAS FOUND:

DEPTH OF 3.7M AT POSITION 46-13-15.6.63N, 63-09-14.12W.

NOTE THAT DEPTHS ARE BELOW CHS CHART DATUM AND HORIZONTAL POSITIONS ARE BASED ON NAD 83.

M2070/17 - NORTHUMBERLAND STRAIT - P.E.I. - Chart 4405 - Issued on 2017-10-09
OCTOBER 10, 2017 DREDGING OPERATIONS WOOD ISLANDS HARBOUR BASIN POSITION 45 56 55.176N 062
45 06.048W. MATERIAL DISPOSED VIA PIPELINE TO APPROXIMATE POSITION 45 56 56.652N 062 44 56.544W.
CONTACT ON SITE SCOTT GAUDETTE 902-856-0868.

M2067/17 - NORTHUMBERLAND STRAIT - P.E.I. - Chart 4403 - Issued on 2017-10-06 GRAHAM POND SOUTH BREAKWATER LIGHT - LL 960 MAY BE UNRELIABLE.

M2035/17 - NORTHUMBERLAND STRAIT - P.E.I. - Chart 4406 - Issued on 2017-10-03 CONFEDERATION BRIDGE LIGHT - LL 1017.79 REPORTED EXTINGUISHED.

### **SOUTHEAST COAST - N.S.**

M2139/17 - SOUTHEAST COAST - N.S. - Chart 4241 - Issued on 2017-10-19 UPPER PORT LA TOUR LIGHT - LL 343 TEMPORARILY DISCONTINUED.

M2057/17 - SOUTHEAST COAST - N.S. - Chart 4386 - Issued on 2017-10-05 RED SPAR BUOY REPORTED ADRIFT IN APPROX. POSITION 44 34 23N 063 55 50W.

M2005/17 - SOUTHEAST COAST - N.S. - Chart 4236 - Issued on 2017-10-02
AS A RESULT OF A RECENT SOUNDING SURVEY NEAR LAWRENCETOWN, NOVA SCOTIA, THE FOLLOWING SHOAL DEPTHS WERE IDENTIFIED:

-0.8M AT 44 36 59.573851N, 063 16 48.654616W

1.1M AT 44 38 02.918903N, 063 22 08.057913W

NOTE THAT DEPTHS ARE BELOW CHS CHART DATUM AND HORIZONTAL POSITIONS ARE BASED ON NAD83.

M2002/17 - SOUTHEAST COAST - N.S. - Chart 4386 - Issued on 2017-09-30 ST. MARGARET'S BAY GREEN CAN BUOY DU51 44 37 48.325 N 063 56 45.749 W REPORTED GONE FROM STATION.

M1995/17 - SOUTHEAST COAST - N.S. - Chart 4240 - Issued on 2017-09-28 PORT MOUTON BREAKWATER LIGHT - LL 401.5 REPORTED BURNING AT REDUCED INTENSITY.

M1978/17 - SOUTHEAST COAST - N.S. - Chart 4394 - Issued on 2017-09-25 MOSHER ISLAND - LL 423 FOG SIGNAL NOT OPERATING PROPERLY.

M1968/17 - SOUTHEAST COAST - N.S. - Chart 4236 - Issued on 2017-09-22
AS A RESULT OF A RECENT SOUNDING SURVEY CONDUCTED OF CLAM BAY, N.S., SHOAL DEPTH HAVE BEEN DISCOVERED AS FOLLOWS:

5.1 M 44 39 36.545 N, 062 56 00.67W

PLEASE NOTE THAT DEPTHS ARE BELOW CHS CHART DATUM AND HORIZONTAL POSITIONS ARE BASED ON NAD83.

## **SOUTHWEST COAST - N.S.**

M2111/17 - SOUTHWEST COAST - N.S. - Chart 4328 - Issued on 2017-10-16
A 2017 PUBLIC WORKS AND GOVERNMENT SERVICES CANADA SOUNDING SURVEY OF THE APPROACHES TO THE LUNENBURG HARBOUR WAS COMPARED TO CANADIAN HYDROGRAPHIC CHART 4328 FOR POSSIBLE HAZARDS TO NAVIGATION. WITHIN THE SURVEY COVERAGE AREA, THE FOLLOWING DIFFERENCES WERE FOUND:

- 1. ADD 3 FATHOMS 4 FEET AT 44 20 34.2 N 64 17 27.2 W
- 2. ADD 3 FATHOMS 4 FEET AT 44 20 49.5 N 64 17 33.5 W
- 3, ADD 3 FATHOMS 3 FEET AT 44 20 48,2 N 64 17 37,3 W
- 4. ADD 4 FATHOMS 4 FEET AT 44 21 02.1 N 64 17 54.1 W.

NOTE THAT DEPTHS ARE REFERENCED TO CHS CHART DATUM AND HORIZONTAL POSITIONS ARE BASED ON NAD83(CSRS).